

SKF Technical Bulletin

VKJP 3017 - Importance of the correct boot tightening



AUDI A4, VW Passat, Skoda, Superb



Correct tightening of the boot onto the shaft is crucial to avoid premature failure!




OE Nb: 8D0 498 203 A, 8D0 498 203, 3B0 498 203 A

For the above applications, the correct tightening of the boot onto the driveshaft is crucial to ensure the normal boot lifespan. Incorrect boot mounting can significantly reduce the lifespan of the component and lead to premature failures!

On the back page, you will find some technical instructions to perform a professional repair with a correct boot tightening.

VKJP 3017



VKJP 3017 - Importance of the correct boot tightening

If the small diameter of the boot is tightened too close to the spline of the shaft, the boot coils may tear. If it's tightened too far (Picture 1), the boot will stretch excessively and will cause cracks (Picture 2).



Pic. 1 - Incorrect boot tightening



Pic. 2 - Boot cracks due to incorrect tightening



Pic. 3 - Correct position for boot tightening



Pic. 4 - Slots for correct boot fitting



Before tightening the small boot clamps, ensure the boot is positioned correctly by moving the joint to its extreme angulation. The boot should not look too stretched on one side, and not too compressed on the other side.

[Click here to watch SKF technical videos on Youtube!](#)

© SKF Group 2016

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use

Flash QR code

