4

Adjustment of tappets





### REASON

Remember instructions of mechanic adjustment in order to avoid noises and early wear on cam axis and tappets. For this, we will use a general suggestion for engines XUD7, DW8, DW8B, XUD9TE, XUD9TF.

### INTRODUCTION

Evolution in mechanics leads to the widespread use of hydraulic systems in the adjustment of lobes with valves.

AJUSA offers the most extensive program of hydraulic lifters as well as camshafts. In the assembly of camshfts, in case tappets are used, it is necessary to make the correct adjustment to avoid damages on camshafts and other contact elements.

### VALVE ADJUSTMENT

Before disassembly and adjustment, it is recommended **to let the engine cool**, as expansions may affect measures.



Necessary steps for valve adjustment in engines XUD7, DW8, DW8B, XUD9, XUD9TE, XUD9TF:

- Remove valve cover as indicated in the manufacturer specs.
- > Draw a diagram of the disposition of valves in the engine.



Turn th engine until you place exahust valve nº 1 (next to wheel) at its maximum opening; at this moment, exhaust valve nº 3 and intake valve nº 4 are closed, so we can check the clearance between lifter and lobe with a feeler gauge. Write down the value.





Check exhaust valve nº 4



Check intake valve nº 3



Continue checking the remaining lifters, according to the following table:

EXHAUST Valve	INTAKE Valve	EXHAUST Valve
1	3	4
3	4	2
4	2	1
2	1	3

Nominal working values INTAKE = 0,15 - 0,08 mm EXHAUST = 0,30 - 0,08 mm

Calculate the difference between measured and nominal values. If the difference is over or under the tolerance, proceed with adjustment, increasing or decreasing thickness of the suplement in the mentioned value.

#### EXAMPLE

Tolerance = 0,08 mm

**Measured value exhaust valve nº 4** 0,46 mm

Nominal value for exhaust valves 0,30 mm

Average value - nominal value 0,46 - 0,30 = 0,16 mm → ADJUSTMENT (0,16 > 0,08) Shim should be replaced by one measuring 0,16 mm thicker.

Measured value in intake valve nº 3 0,18 mm

**Nominal value for intake valves** 0,15 mm

#### Average value -nominal value

0,18 - 0,15 = 0,03 mm →NO REGLAJE (0,03 < 0,08).

Before adjustment, it is necessary to disassemble the camshaft following the manufacturer specs.

Disassemble tappet and measure thickness of shim. Before measuring a new suplement it is recommended to degrease it.

Write the obtained value in the diagram of disposition of valves.



The value obtained between measured value and nominal value must be added

or substracted.

A E E A A E E A

\*Measured value \*\*Measured value-nominal value \*\*\*Value of shim

#### New suplement = 2,80 + 0,16 + 2,96 = 0,08 mm

If no suplement that matched the necessary thickness is available, see tolerances.

#### recommendations

- > Clean and lube all parts.
- First, assemble adjustment suplement in the corresponding housing over the valve stem, and then the tappet.
- Once the camshaft has been assembled, check that all valves have been correctly adjusted.