

Technical Bulletin

Mitsubishi Pajero, Shogun, Shogun Sport, Shogun Pinin, L200, L300, Challenger, Strada, Delica - Mainshaft spigot Bearing Failure

Applicable References: ADC43399, ADC43398, ADC43397

Applications: Various Mitsubishi 1981 ->

Date Issued: 05/2006

We have encountered several cases of spigot bearing failure on some Mitsubishi models.

The flywheel should be carefully checked or replaced when installing a new clutch assembly.

The following points should be noted during routine clutch replacements:

A seized flywheel bearing may cause the transmission spigot bearing to spin and wear inside the bearing race or the outer bearing casing to spin and wear inside the flywheel.

Flywheel bearing failure will often cause transmission spigot bearing failure and misalignment damage to the clutch assembly.

The bearing is pressed into the flywheel with an interference fit. Care should be taken when installing this bearing. Ensure the race is not 'pinched' when fitted.

It is advisable to replace the spigot bearing as a precautionary measure whenever the clutch assembly is removed.

Picture showing wear between the transmission spigot and the inside of the bearing inner race, due to the spigot bearing seizure.



Three spigot bearings are available from Blue Print:
ADC43399 (40mm), ADC43398 (35mm), ADC43397 (32mm)

Between them, these bearings are suitable for the following Mitsubishi UK specification and Japanese Import model types:

Pajero V24, V44, V47, V26, V46, V23/V43, V25/V45, V55, V34, V21

Shogun V24, V44, V23/V43, V26/V46, V25/V45, V68/V78, V64

Shogun Sport K96W

Shogun Pinin H66

L200 K74, K64, K76, KB4

L300 L032 P02/P12, P03/P13, L039, P05/P15

Challenger K96W, K94W, K97W

Strada K74

Delica P*8W, P*SW



www.blue-print.com

Blue Print is a bilstein group brand

Disclaimer: Any technical tips are produced in good faith. Ferdinand Bilstein UK Ltd. always recommend that vehicle maintenance and diagnostics are only carried out by suitably experienced people using appropriate tools in a safe manner within a workshop environment. Ferdinand Bilstein UK Ltd. and their customers cannot be held responsible for the correctness of, or misinterpretation of the above technical tips. Images shown are for illustrative purposes only and may not be representative of the products or vehicles described.