

SWAG 60 93 6444

to fit:
Renault 1.6 16V
Engine: K4M

SWAG®



EN

Timing Belt Kit with Water Pump

Problem

Intermittent starting and a rattling noise coming from the top of the engine when first started.

Cause

Internal failure of the camshaft gear/dephaser pulley – this controls the adjustment of the variable valve timing.

Solution

Replace the variable camshaft timing pulley (SWAG 60 93 6415). It is also recommended that during the replacement of this pulley, the complete timing belt kit – including the water pump (SWAG 60 93 6444) – should also be replaced for a complete repair.

For more technical information please visit: partsfinder.bilsteingroup.com