echnical data can be subject to change



SWAG 10 92 1530,

10 92 7880

To fit:

Mercedes-Benz CLS-Class (219), E-Class (211), SL-Class (230, 231)



10 92 1530 (old implementation)



10 92 7880 (new implementation)



Control Arm Bush

Problem

When repairing the control arm on any of the Mercedes-Benz models listed above, the replacement control arm bush is of a different design to the one that has been removed.

Cause

During the course of production of the Mercedes-Benz models listed above, improvements were made to the noise, vibration, and harshness characteristics of the suspension components. A new hydraulic control arm bush was developed to replace the original rubber metal design, however the manufacturer continued to offer both versions as service parts.

Solution

If the original bush that is removed from the control arm is the early rubber metal design, SWAG recommends installing the improved hydraulic version. If this is the case, SWAG suggests replacing both control arm bushes at the same time to improve the vehicle's noise, vibration, and harshness characteristics.