



EXPERT TIP

CAMSHAFT ADJUSTER AUDI-VW 1.4 TFSI & 1.6 ENGINES

ENGINE TIMING CONTROL | 11314 | 11316



Important notes

Inaccurate manufactured camshaft adjusters by the manufacturer lead to premature chain wear. This problem mainly affects timing chains for Audi-VW 1.4 TFSI & 1.6 engines.



Risk of injury

For your own safety wear hand, ear and eye protection during maintenance and repair work.



Please note the following carefully

1. install latest version of camshaft adjuster
2. update the system of the control unit after replacement
3. reset engine's learn values

VAICO recommends replacing the timing chain set V10-10010-BEK together with the camshaft adjuster V10-4408! Both items are also available together as Expert Kit+ V10-10010. In addition to the timing chain kit and camshaft adjuster, this kit also includes a gasket, accessories and a suitable amount of engine oil.



CAMSHAFT ADJUSTER



X-Ref 03C 109 088 E*

V10-4408

TIMING CHAIN KIT



X-Ref 03C 109 158 A kit2*

V10-10010-BEK

TIMING CHAIN KIT



X-Ref 03C 109 158 A kit*

V10-10010

* For detailed vehicle information, please refer to the vehicle lists under www.autoteile.de.