


NEW PRODUCT HIGHLIGHT | JAN2020



febi 109176

to fit:
Various Volkswagen, Audi, Seat and
Skoda models



EN

Adjustment motor for recirculating air flap

Function

To operate the interior heater recirculating air flap, for the mixture of the air into the cabin, which is operated by the heater controls.

Cause of Failure

A clicking noise from behind the glovebox area, after the engine is started. This noise is from the heater recirculation air flap motor, due to a worn gear drive.

For more technical information please visit: partsfinder.bilsteingroup.com