



Anti-roll bar kits with mounts and connecting rods



Everything for repairs!

Road debris, road salt and other external factors are frequent causes of damage to the anti-roll bar's coating (see Fig. 1). The worn coating of the anti-roll bar often gives rise to squeaking noises.



Please note!

When the anti roll paint protection is damaged around the mounting points, always replace the anti-roll bar along with the rubber mounts.



Fig.1

For this reason, febi offers the anti-roll bar kit, e.g. for VW Golf IV febi no. 36630 (see Fig. 2), which includes not only the fitting kit but also the anti-roll bar. This combination enables a professional repair and avoids complaints. This will save time and money for both the workshop and their customer!



Fig.2 Anti-roll bar kit with mounts and connecting rods febi no. 36630

Your febi advisor will be pleased to tell you about other anti-roll bar kits!

For more technical information please visit: partsfinder.bilsteingroup.com