

SERVICE INFO



Replacing tensioner pulleys 531 0037 10 and 531 0353 10 (front end accessory unit drive) in 531 0241 10

Vehicle manufacturers: Citroen, Peugeot

Models:

Citroen: Berlingo, Saxo
Peugeot: 106 I, 106 II, 306, partners

Engines: 1.0, 1.1, 1.4, 1.6

OE Nos.: 6453.C5 (replaced)
6453.G4 (replaced)
6453.S4 (replaced)
6453.S5 (new)

Part No.: 531 0037 10 (replaced)
531 0353 10 (replaced)
531 0241 10 (new)




Image 1: Illustration of the individual tensioner pulleys and their differences

The two tensioner pulleys with part numbers 531 0037 10 and 531 0353 10 (installed in the front end accessory unit drive) are now redundant; they have been replaced by part number 531 0241 10.

Key to image 1:

- (1) 531 0037 10
- (2) 531 0353 10
- (3) 531 0241 10
- (4) Washer 8.4x19x4 mm

Schaeffler Automotive Aftermarket has followed in the footsteps of vehicle manufacturers Citroen and Peugeot, who have also replaced the product.

Note:

To offset the difference in height, a washer measuring 4 mm in thickness is included with tensioner pulley 531 0241 10.



Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 07.2010

INA 0061

Subject to technical changes

© 2010 Schaeffler Automotive Aftermarket

Any reference to replacement part numbers for vehicle manufacturers is for comparison purposes only.

For further information:

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

www.Schaeffler-Aftermarket.com

* Calls from within the UK 08457 001100

