



Service Info



Visual differences

between over-running alternator pulleys 535 0214 10 and 535 0229 10

Manufacturer: Honda

Models: Accord VIII, Accord IX, Civic VIII, CR-V II, CR-V III, FR-V

Engines: 2.2 i-CTDi, 2.2 I-DTEC

Part no.: 535 0214 10
535 0229 10

OE numbers: 31141-RBD-E02
31141-RL0-G01



Image 1: Over-running alternator pulley 535 0214 10

Two different over-running alternator pulley versions may be installed in the models mentioned above.

Image 1 shows the production version (left) and the aftermarket version (right) of over-running alternator pulley 535 0214 10.

Image 2 shows the production version (left) and the aftermarket version (right) of over-running alternator pulley 535 0229 10.



Image 2: Over-running alternator pulley 535 0229 10



Image 3: INA special tool Part number 400 0241 10

A special tool is required to remove and install the over-running alternator pulley (image 3).

The over-running alternator pulleys fully comply with the technical requirements and only differ in their appearance.

Note the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com.

Phone: +44 (0) 14 32 264 264*
Fax: +44 (0) 14 32 375 760
info@luk-as.co.uk
www.schaeffler-aftermarket.com

* Calls from within the UK 08457 001100

SCHAEFFLER
AUTOMOTIVE AFTERMARKET

