SERVICE-INFO



Information regarding over-running alternator pulley 535 0219 10

Manufacturer: Hyundai, Kia, Toyota

Models:	
Hyundai:	Sonata V, Sonata VI
Kia:	Magentis, Carens III
Toyota:	Auris, Corolla, Corolla Verso
Engines:	
Hyundai:	2.0, 2.0 CVVTi, 2.4, 2.4 GDI
Kia:	2.0, 2.0 CVVT, 2.4
Toyota:	1.4 D, 1.4 D-4D
OE numbers:	
Hyundai:	37321 - 25301
Kia:	37321 - 25301
Toyota:	27415 - 33050
Part no.:	535 0219 10

Different versions of the over-running alternator pulley can be installed in the models mentioned above.

Image 1 shows the two over-running alternator pulleys installed by the respective vehicle manufacturer.

Any reference to replacement part numbers for vehicle manufacturers is for comparison purposes only.



Image 1: Previous designs Toyota (silver), Kia/Hyundai (black)

Schaeffler Automotive Aftermarket now offers **one** over-running alternator pulley **(Image 2)** that covers the models listed from all three manufacturers.

Note:

The new over-running alternator pulley from Schaeffler Automotive Aftermarket meets the technical requirements in all points and differs only visually.

A special tool is required to remove and install the over-running alternator pulleys (Image 3).



Image 2: New design



Image 3: INA special tool Part number 400 0241 10



Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 09.2011 INA 0080 Technical subject to change © 2011 Schaeffler Automotive Aftermarket



For further information:

Phone: +44 (0) 14 32 264 264* Fax: +44 (0) 14 32 375 760 Info@LuK-AS.co.uk www.Schaeffler-Aftermarket.com * Calls from within the UK 08457 001100