



## Service Info



# Visual differences

## in over-running alternator pulley 535 0233 10

Manufacturer: Suzuki

Model: Jimny (FJ)

Engine: 1.5 DDiS

Part no.: 535 0233 10

OE number: 31171-84A10



Figure 1: Previous design



Figure 2: New design

As part of our continuous efforts to improve our products, modifications have been made to the over-running alternator pulley with part number 535 0233 10.

This Service Information sheet shows the visual features of the previous version (Figures 1 and 3) and the new version (Figures 2 and 4).



Figure 3: Previous design



Figure 4: New design

In the new version, the inner ring on the rear side has been extended, so the spacer that can be seen in Figure 3 is no longer required.

During the transition period, we may have mixed stocks of both types.

Both versions comply with the technical specifications and can be used without restrictions.

Note the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under [www.schaeffler-aftermarket.com](http://www.schaeffler-aftermarket.com) or [www.RepXpert.com](http://www.RepXpert.com).

Phone: +44 (0) 14 32 264 264\*  
 Fax: +44 (0) 14 32 375 760  
 info@luk-as.co.uk  
 www.schaeffler-aftermarket.com

\* Calls from within the UK 08457 001100

**SCHAEFFLER**  
 AUTOMOTIVE AFTERMARKET

