



## Service Info



# Over-running alternator pulley 535 0275 10

## Visual differences

Manufacturer: BMW

Models: 1' (E81/E82/E87/E88)  
3' (E90/E91/E92/E93)  
X1 (E84)

Engines: all N43  
all N55

Part no.: 535 0275 10



Figure 1: Previous design



Figure 2: New design

As part of our continuous efforts to improve our products, modifications have been made to the over-running alternator pulley with part number 535 0275 10.

This Service Information sheet shows the visual features of the previous version (Figure 1) and the new version (Figure 2).

During the transition period, we may have mixed stocks of both types.

The two versions differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.

Please observe the vehicle manufacturer specifications!

### You want more? We can help!

Phone: +44 (0) 1432 264 264\*

Fax: +44 (0) 1432 375 760

[hfd-info@schaeffler.com](mailto:hfd-info@schaeffler.com)

[www.schaeffler-aftermarket.co.uk](http://www.schaeffler-aftermarket.co.uk)

\* Calls from within the UK 08457 001100

