

SKF Product Information

VKBA 6737 – Mandatory replacement of the nut



BMW X3 (F25), X4 (F26)



Mandatory replacement of the nut during the wheel bearing fitting



Bearing OE Nb: 33 40 6 787 015

To ensure a complete and professional repair, SKF has added a nut in the wheel bearing kit from batch code 248 R. It is mandatory to replace the old nut as it can be damaged during the bearing removal or when fitting the new one.

VKBA 6737



Nut included in the wheel bearing kit

YouTube [Click here to watch SKF technical videos on Youtube!](#)

© SKF Group 2019

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use

