



# VKJP 90015

Product Information - February 2015

VKJP 90015



LADA 110, 111, 112, Samara



Kit content: VKJP 90015



Following customers' demands, SKF has recently launched a new Driveline kit - VKJP 90015. This Multipack kit contains:

- 15 identical boots
- 15 grease bags
- 15 short clamps
- 15 long clamps
- 15 circlips
- 15 nuts

Inside the Multipack kit, there are 15 plastic bags that contain the single kit composed as follow: one boot, one nut, one circlip and 2 clamps. The 15 grease bags instead, are loose in the multipack box.

**Note!** The boot kits contained in the VKJP 90015 are interchangeable with VKJP 3008.

## VKJP 90015



For a professional repair when tightening the ear clamps, it is recommended to use the SKF tool VKN 401. Incorrect tightening of the clamps can cause premature failure of the CV-Joint!



Tightening tool: **VKN 401**

Install confidence  
[www.vsm.skf.com](http://www.vsm.skf.com)

© SKF is a registered trademark of the SKF Group.

© SKF Group 2015

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use of the information contained herein.

February 2015