



VKPC 91416

Technical Bulletin – April 2015



TOYOTA Carina VI, Corolla VII/VIII – 1.6 (Engine code 4A-FE)




VKPC 91416 Fitting instructions – only for **AISIN** brand marked on the water pump body



OE Nb: 16110-19205


Installation of the SKF Water pump VKPC 91416

For the above mentioned applications, Toyota (OEM) has used during the carline production three different water pump suppliers. The different brands can be identified on the water pump body (see below).




"AISIN" Brand

OE Nb: 16110-19205



"Aisan" Brand

OE Nb: 16110-19146



"SEM" Brand


OE Nb: 16110-09021



Note! SKF Water pump VKPC 91416 can only be installed on engines equipped with an Aisin waterpump and with the corresponding AISIN back-housing.

Mixing-up with the 2 other waterpump brands Aisan or SEM will lead to following issues:

- Hitting/Scrapping of the VKPC 91416 impeller at the Aisan or SEM back-housing.
- Difficulties/Impossible to install VKPC 91416 since impeller blades are too big/tall for the backhousing.
- Coolant leakage: AISIN and SEM are not interchangeable. (See below)



Conclusion and recommendations

- Always check the waterpump brand fitted on the car before starting the repair.
- VKPC 91416 is designed to replace ONLY an AISIN OE water pump combined with an AISIN back-housing.
- Mixing up all other sorts of combinations with AISAN or SEM back-housings and gaskets will lead to serious problems as described above.

Install confidence
www.vsm.skf.com

© SKF is a registered trademark of the SKF Group.

© SKF Group 2015

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless prior written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use of the information contained herein.

