

E765L for DAF LF 45 and LF 55 from year of construction 2006

Due to an OE modification on the housing cover DAF 1951885 and the corresponding filter insert DAF 1914366, the Hengst filter E765L only corresponds to OE part DAF 1679397 and cannot be installed in the vehicles DAF LF 46 and LF 56 from May 2013.

The changes can be seen in the two illustrations below.



Cover for DAF LF 45 / LF 55
E765L can be installed



Cover for DAF LF 46 / LF 56
E765L can **not** be installed