



LuK Service Info



LuK RepSet 625316509 and 625321209

Pressure plate does not fit the flywheel pin centering

Manufacturer: Fiat

Models: Ducato 2J

Model years: 08/2008 to 12/2011

Engine: F1A/2.3 l/88 kW

LuK RepSet: 625 3165 09 (up to model year)
625 3212 09 (from model year)

See parts catalog for current assignment

For the above vehicle model, the clutch has changed during the production period. As the transition to ongoing production has been completed, a precise change point is not possible.

It is therefore possible vehicles contain clutches “up to model year,” although according to the chassis criteria of the clutch “from model year” should be installed.

If, in the event of a repair, the pressure plate of the LuK RepSet selected in the catalog media does not match the pin centering of the flywheel, the LuK RepSet of the other build period must be selected.



Figure 1: Pressure plate of RepSet 625 3165 09 (for vehicles up to model year)



Figure 2: Pressure plate of RepSet 625 3212 09 (for vehicles from model year)

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk

SCHAEFFLER
REPXPERT