



LuK Service Info



Concentric slave cylinder 510 0183 10

Replacing the plastic hydraulic line when installing metal versions

Manufacturer: Chevrolet
Opel
Saab

Models: CRUZE
MALIBU
ORLANDO
ASTRA
CASCADA
INSIGNIA
ZAFIRA
9-5

OE-parts:
Connector: 55 563 644
Line fixing: 55 576 804 green with Start Stop
90 522 038 black without start stop
Hydraulic line: 24 428 856

See parts catalog for current vehicle assignment.

For the vehicle manufacturers and models mentioned above, the material of the CSC (Concentric Slave Cylinder) and the design of the hydraulic connection were changed during the production period. Therefore, different CSC versions can be found during a clutch repair.

A defective plastic central release (Fig. 1) cannot be replaced with the current metal version (510 0183 10) without a new hydraulic connection line. In this case, the metal hydraulic line and various guide and connection parts from the vehicle manufacturer (Fig. 2) must be used.



Figure 1: Hydraulic line of the plastic CSC



Figure 2: Hydraulic line, guide, and connection parts from the vehicle manufacturer

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264
Fax: +44 (0) 1432 375 760
aftermarket.uk@schaeffler.com
www.repxpert.co.uk

SCHAEFFLER
REPXPERT