



## LuK SERVICE INFO



# Features of applicability of clutch kits

## Wrong application of RepSet clutch set

Manufacturer: Ford  
Mazda

Models:  
Ford: B-MAX (JK)  
B-MAX Van (JK)  
ECOSPORT  
FIESTA VI (CB1, CCN)  
FIESTA VI Van  
KA+ III (UK, FK) | FIGO  
TOURNEO COURIER B460 MPV  
TRANSIT COURIER B460 limo  
TRANSIT COURIER B460 MPV  
Mazda: 2 (DE\_, DH\_) | DEMIOOE

OE-No:

Ford:  
1212061 1434878 1457641 1474323  
1480708 1495872 1514143 1547820 1548409  
1678828 1708209 1742518 1804545 1805271  
1826509 1827270 1830995 1837710 1852056  
2115219 2245763 2287090 2S61-7A564-CA  
2S61-7A564-CB 3M51-7A564-AG 3M51-7A564-AH  
5278677 7G91-7A564-AA 7G91-7A564-AB  
7G91-7A564-AC 8V21 7540 DE 8V21 7540 DF  
8V21 7540 DG 8V21 7540 DJ 8V21 7540 FA  
8V21 7540 HA 8V21 7550 DC 8V21 7550 DE  
8V21 7563 DC 8V21 7563 DD 8V21 7563 HB  
8V21-7A564-AA 8V21-7A564-AB 8V21-7A564-AC  
8V21-7A564-AD AV61-7A564-AC BM55-7A564-AB  
RM 8V 21754 ODF RM 8V 21754 ODG  
RM 8V 21754 OFA

Mazda:  
DK49-17-ZX1A DK49-17-ZX1B  
Y604-16-490E Y604-16-490F

Art.-Nr: 622 3231 33

For current assignment see parts catalog




Image 1: LuK RepSet art.-nr. 622 3231 33

In some cases, the wrong part may be installed in the wrong vehicle just because two products are the same size and can be installed.

Even if two products have the same dimensions, their technical specifications and transmitted torque capacity may differ.

In this case, if the part is incorrectly selected, the product may fail quickly, and the incorrect application will void the warranty rights.

The most accurate way to determine which vehicle a part is suitable for is to use the Schaeffler online catalog. When selecting a part, always consult the Schaeffler catalog.

Please observe vehicle manufacturer recommendations & specifications.

### You want more? We can help!

Phone: +44 (0) 1432 264 264  
Fax: +44 (0) 1432 375 760  
aftermarket.uk@schaeffler.com  
www.repxpert.co.uk

SCHAEFFLER  
REP>XPERT