




Installation Oil Separator, crankcase ventilation


B20.960 | B20.980 | B20.990 | B21.010

Audi | VW | Porsche

 **B20.960** # 06E 103 547 AD | 06E 103 547 AF | 06E 103 547 N


 **B20.980** # 06E 103 547 AB | 06E 103 547 AH | 06E 103 547 H | 06E 103 547 S

 **B20.990** # 06E 103 547 G | 06E 103 547 R


 **B21.010** # 06E 103 547 E | 06E 103 547 P




1.



2.



3.



B20.960



B20.980



B20.990



B21.010

ElringKlinger AG | Aftermarket Division

Max-Eyth-Straße 2 | D-72581 Dettingen/Erms

Fon +49 7123 724-799 | Fax +49 7123 724-798

service@elring.de | www.elring.com

SI 06/2024



Das Original