

# AXIAL JOINT KITS WITH STEERING GAITER

TECHNICAL INFO NO. 1052

MANUFACTURER	VEHICLE EXAMPLE*	KIT	AXIAL JOINT	STEERING GAITER
<b>BMW</b>	"3" series (E36)	915015S	915015	945002
<b>Citroen/ Peugeot</b>	Jumper I + Boxer I	915927S	915927	945818
	Jumper I + Boxer I / Jumper II + Boxer II	915927S1	915927	945915
<b>Ford</b>	Sierra 82-86	915215S	915215	945207
		915215S1	915215	945205
	Escort/Orion 90-95 and Escort 95-01	915205S	915205	947003
		915218S	915218	945213
	Fiesta 89-96	915211S	915211	945208
	Focus 98-05	915264S	915264	945213
	Mondeo 92-96 and Mondeo 96-00	915233S	915233	945214
	Transit 85-91, Transit 91-94, Transit 94-00	915247S	915247	945206
Transit 00-06	915273S	915273	945217	
<b>Opel</b>	Corsa C	915379S	915379	945308
	Astra G + H/Zafira A	915359S	915359	948402
	Vectra B	915353S	915353	945305
915353S1		915353	945306	
<b>Renault/ Opel</b>	Trafic I (from 03/89), Arena	915908S	915908	945309
		915908S1	915908	945502
<b>Renault</b>	R25	915512S	915512	945502
		915512S1	915512	945504
		915512S2	915512	945503
<b>Seat</b>	R19	915507S	915507	945502
	Toledo	915449S	915449	945410
<b>Seat/VW</b>	Cordoba/Vario 93-02, Ibiza 93-02, Toledo 92-96	915436S	915436	945401
	Leon 00-06, Toledo 99-04, New Beetle	915774S	915774	945703
<b>VW</b>	Transporter T4	915483S	915483	945408
		925484S	925484	945408

\*Approximate model allocation: for details please refer to our catalogue, TecDoc or our online catalogue at [www.ruville.de](http://www.ruville.de)



Fig. 1: Axial joint kit with steering gaiter

Like all other parts made of plastic, steering gaiters are subject to natural aging so that they become brittle and start to crack after a certain period of time.

Failure of the axial joint is therefore usually caused by a defective steering gaiter.

Dirt and water penetrate the joint, causing premature failure.

RUVILLE therefore offers axial joint kits including steering gaiter for dealing with repairs to the axial joint in selected vehicle types.

### Advantages of a complete change (axial joint and steering gaiter):

- There is no risk of having to replace a newly fitted axial joint again after only a short period of time because of an old, defective steering gaiter.
- Cost savings for reworking
- No time-consuming repeat orders
- Greater customer satisfaction



### INFORMATION

Corresponding spare parts can be found in our online catalogue at [www.ruville.de](http://www.ruville.de)

Where reference is made to the spare parts numbers of the vehicle manufacturers, this is only for the purposes of comparison.

### IMPORTANT NOTE!

The above table gives an approximate overview of the complete kits available in the RUVILLE range. Axial joints and steering gaiters are available singly for many other vehicles.

Please comply with the instructions issued by the vehicle manufacturer!

EGON VON RUVILLE GMBH

Billbrookdeich 112 • 22113 Hamburg • Germany  
 Phone: +49 (0)40 73344-0 • Fax: +49 (0)40 73344-199  
[info@ruville.de](mailto:info@ruville.de) • [www.ruville.de](http://www.ruville.de)

