

UPPER MOUNTING POSITION

Punto




FI054EU



Mechanical steering
Caster angle 1° 30' *

Power assisted steering
Caster angle 2° 30' *

FRONT




FRONT



*Car Manufacturers reserves the right to amend all technical data, Monroe® is not responsible for possible data changes.

Pump reservoir for power assisted steering




Identification of a vehicle with power assisted steering

TIGHTENING TORQUES		daN.m
A	Upper mounting bolts	4.9
B	Top stem nut	5.1
C	Lower mounting	7


PUNTO 55 , 60 , 75 , 90

94 >



PUNTO GT , D , TD

94 >



These shock absorbers do not possess the same operating characteristics. After shock absorber change, the toe angle will not be correct anymore. GEOMETRY CHECK AND ADJUSTMENT IS NECESSARY

E4259	REFLEX®	E4477
11194	ORIGINAL®	11647