

SWAG 33 10 1501

SWAG[®]

To Fit: Audi A3 (8V), Q2 (GA)
SEAT Ateca (KH), Leon (5F)
Škoda Karoq, Kodiaq, Octavia III, Superb III
VW Atlas (CA), Golf 7 (5G, BQ, BA, BV, AU,
AM, AN, BX), Teramont (CA),
Tiguan 2 Allspace (BW2),
Touran 2 (5T)



EN

Ignition Switch

Problem

The engine remains running when the ignition key is turned to the 'off' position but stops when the key is removed. Using a suitable diagnostic tool can show the following fault codes:

B11A511 – S contact, short to ground

B12E512 – Ter.15: signal, short to B+

B12E612 – Actuation relay terminal 15 load, short to B+

Cause

A fault can occur in the switch caused by internal tolerance issues which prevent the contacts from aligning correctly.

Solution

Check the continuity of the wiring loom to the ignition switch. If the readings are correct then proceed with changing the ignition switch. SWAG replacement part 33 10 1501 is manufactured to match the latest (modified) version. SWAG also has the ignition lock housing in range under article number 30 93 6044.

For more technical information please visit: partsfinder.bilsteingroup.com