


### Additional core acceptance criteria


In order to ease the return procedure for the workshops, TRW has decided to expand the core return acceptance criteria for all cores of EPB calipers.

From now on, TRW accepts the following damages on the electric part of EPB calipers:

#### Cracked actuator housing (Fig.1)



#### Cracked plug connector (Fig.2)



TRW accepts the damages on the electric part of EPB calipers under the condition, that the metal part of the caliper corresponds to the general core acceptance criteria, and is therefore without damage.

The complete core return criteria, as described in the TRW Service Information XZS119, needs to be precisely observed!

