

Fitting instructions for front wheel bearing sealing ring

Manufacturer: Audi, Seat, Škoda, VW

Models:

Audi A2 (8Z0)

Seat Cordoba (6L2)
Ibiza (6L1)

Škoda Fabia (6Y2, 6Y3,
6Y5)
Roomster (5J)

VW Polo (9N)
Fox (5Z1)

Item no.: 713 6104 70 (FAG-Kit)
OE-No.: 14" 6Q0407623B / E
(Sealing Ring)

Item no.: 713 6105 70 (FAG-Kit)
713 6105 80 (FAG-kit)
OE-No.: 13" 6Q0407623C
(Sealing Ring)



Figure 1: The Sealing Rings could differ in design and color!

Contamination on the inside of the wheel bearing can result in the failure of the wheel bearing. The wheel bearing seal is also affected by this, resulting in the damage mentioned above.

If you are replacing a wheel bearing, you must also use a sealing ring, which is placed on the drive shaft taper (see Fig. 1).

Note:

As soon as the sealing rings are available, they will be included in the respective kits. This will prevent the sealing rings being mixed up or incorrectly assigned.



Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 10.2009 (replaces 09.2009)
FAG 0007

Technical subject to change

© 2009 Schaeffler Automotive Aftermarket oHG

For further information:

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

www.Schaeffler-Aftermarket.com

* Calls from within the UK 08457 001100