



Service Info



Truck Hub Unit (THU)

Observe installation orientation

Manufacturers: DAF, Iveco, MAN, Mercedes-Benz, Scania, Dana, Gigant

Part No.: 805003CA.H195
805011C / 805011.03.H195
805012.06.H195
805092.07 / 805092.07.H195
571762.01.H195
803194.26 / 803194.26.H195
805003A.H195



Fig 1: Truck Hub Unit with seal ring (left) and beveled edge (right) on the bearing inner ring

The bearing units listed above must be installed in the correct orientation. Although this is determined by the shape of the axle journal and by the shape of the bearing inner ring of the THU, this Service Info is provided for further clarification.

The key difference can be seen on the bearing inner ring. Some bearing units have an o-ring (Fig. 2) on the inner face, where other bearings have a beveled or rounded edge (Fig. 3). The following table lists the feature and the installation orientation of the bearing units.



Fig 2: Truck Hub Unit with o-ring




Fig 3: Truck Hub Unit with beveled edge

Article number	Feature / installation orientation
805003CA.H195 805011C / 805011.03.H195 805012.06.H195 805092.07 / 805092.07.H195	o-ring / faces inward
571762.01.H195 803194.26 / 803194.26.H195 805003A.H195	Beveled edge / faces inward

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264
Fax: +44 (0) 1432 375 760
aftermarket.uk@schaeffler.com
www.repxpert.co.uk



SCHAEFFLER

REP>XPERT