



FAG Service Info



Installation note 713 6103 20

Remove the ABS sensor ring on vehicles without ABS

Manufacturer: Seat
Volkswagen

Models:
Seat: Arosa (6H1)
Cordoba (6K1, 6K2)
Cordoba Vario (6K5)
Ibiza II (6K1)
Volkswagen: Lupo I (6X1, 6E1)
Polo (6N2)
Polo Variant (6V5)
Polo III (6N1)
Polo III Classic (6V2)

Part no.: 713 6103 20

See parts catalogue for current assignment

Schaeffler Automotive Aftermarket offers the wheel bearing kit with part number 713 6103 20 for the vehicles listed above. It is intended for vehicles both with and without ABS.

If the wheel bearing is installed on vehicles without ABS, the ABS sensor ring must be removed from the new wheel hub before installation. This can be done with simple garage equipment, for example with a tyre lever.

If the ABS sensor ring is not removed on vehicles without ABS, this could lead to damage after installation.



Image 1: The wheel bearing kit with part number 713 6103 20 is intended for vehicles with and without ABS.



Image 2: The sensor ring must be removed if the wheel bearing is installed in vehicles without ABS. This can be done using a tyre lever, for example.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk

SCHAEFFLER
REP>XPERT