

# febi 21530, 27880


**To fit:**

Mercedes-Benz CLS-Class (219),  
E-Class (211), SL-Class (230, 231)



febi 21530 (old implementation)



febi 27880 (new implementation)

EN

## Control Arm Bush

**Problem**

When repairing the control arm on any of the Mercedes-Benz models listed above, the replacement control arm bush is of a different design to the one that has been removed.

**Cause**

During the course of production of the Mercedes-Benz models listed above, improvements were made to the noise, vibration, and harshness characteristics of the suspension components. A new hydraulic control arm bush was developed to replace the original rubber metal design, however the manufacturer continued to offer both versions as service replacement parts.

**Solution**

If the original bush that is removed from the control arm is the early rubber metal design, febi recommends installing the improved hydraulic version. If this is the case, febi suggests replacing both control arm bushes at the same time to improve the vehicle's noise, vibration, and harshness characteristics.

For more technical information please visit: [partsfinder.bilsteingroup.com](https://partsfinder.bilsteingroup.com)