




febi 30076 30080, 34700

**To Fit:**

Mercedes Benz various models: 123, 124 (E-class), 201 (C-class), 460, 461, 463 (G-class), 601, 602, 611 (T1) with M102 engine



EN

Thermostat Housing

Problem

Coolant leaking from the plastic thermostat housing.

Cause

Continuous exposure to heat cycles and vibrations when the engine is operating; this can cause the housing to warp or fracture.

Solution

febi has developed an improved aluminium thermostat housing with connector, banjo bolt, and two sealing rings for a complete repair (febi 34700).

For more technical information please visit: partsfinder.bilsteingroup.com