



febi 32418, 103186



To Fit:

Ford, Mazda, and Volvo various models



Control Arm Bush

Problem

Uneven tyre wear and misaligned front suspension.

Cause

Worn lower suspension control arm control bush.

Solution

febi provides an economical repair solution; the control arm bush can be replaced rather than needing to replace the entire suspension control arm. When replacing this bush, it is important that the alignment of the original control arm bush is followed. If the bush is not aligned correctly on the shaft of the suspension arm, there is a risk of premature failure and a shortened lifetime of the component.

There is a special tool available from the vehicle manufacturer to assist in the replacement of the control arm bush.

By using this tool, it can be ensured that the installation position and press-fit depth of the bush will be correct.



Scan the QR code to watch the febi control arm bush kit replacement video or watch it online at:

[youtube.com/ferdinandbilstein](https://www.youtube.com/ferdinandbilstein)

For more technical information please visit: [partsfinder.bilsteingroup.com](https://www.partsfinder.bilsteingroup.com)