



febi 36542

to fit:
all Mercedes-Benz 5-gear
automatic transmissions



Repl. no. 140 270 11 61 S1



febi 36542



Conductor Plate Kit for automatic transmissions

Problem


The sensors of the conductor plate stick together due to deposits in the automatic transmission fluid. This results in gear change malfunctions in the transmission.

SOLUTION

For this reason, febi supplies the complete kit febi 36542 which includes both the conductor plate febi 32342 and also the plug for automatic transmissions febi 36332. This combination enables a professional repair and avoids potential complaints. That saves time and money for both workshop and customer!

Please Note!

Always replace the plug at the same time as replacing the conductor plate. Otherwise leaks may occur at the outlet from the conductor plate. As a result the oil perforates the seal and can therefore get into the automatic transmission control unit via the wiring loom and lead to damage in the control unit.



febi 32342



febi 36332

febi also supplies the conductor plate and plug separately.

For more technical information please visit: partsfinder.bilsteingroup.com