



febi 37000

to fit:

All models of the Ford Focus 1
except for RS/ST170



Repl. no. 1 064 128 S1



EN

All you need for professional repairs!

Control arm including fitting materials

Problems may arise when replacing the rear control arm (febi no. 32582) due to severe corrosion between the rubber mounts and the mounting bolts. Often the only way to sever the connection is by destroying the bolts. As a result, it is necessary to replace the nuts and bolts as well. However, the control arm is frequently supplied by the manufacturer without the necessary fitting materials.

febi has the solution for a timely and efficient repair:

febi now also supplies these control arms as a ProKit with the appropriate nuts and bolts (febi no. 37000). This complete repair kit enables a professional repair without the need for additional sourcing trips. That saves time and money for both workshop and customer! Anyone using a ProKit can safely assume that it contains all the parts necessary for the repair.

**Note!**

The eccentric bolt and eccentric washer are used to set the camber which is absolutely imperative after replacing the control arm.

For more technical information please visit: partsfinder.bilsteingroup.com