

TECHNICAL REPORT

How to select the correct
thickness for cylinder head
gasket ref | 101597X0

SCOPE

Advise our customers about the **correct cylinder head gasket thickness** that must be selected according the number and distribution of notches in 1KD-FTV engines of Toyota

DESCRIPTION

It is well-known by mechanics and engine rebuilders that there is generally a **large variety of thicknesses** of cylinder head gaskets for diesel engines. In some cases, the number and position of the notches is different between gaskets manufacturers, so choosing the correct thickness for the head gasket could be difficult.

In order to help our customers, a comparison between notches from OEM and AJUSA cylinder head gasket for 101597X0 part number and its **different thicknesses** is showed below.



AJUSA REF.	THICKNESS	NOTCHES DISTRIBUTION AJUSA	NOTCHES DISTRIBUTION OEM
10159700	0,85 mm		
10159710	0,90 mm		
10159720	0,95 mm		
10159730	1,00 mm		
10159740	1,05 mm		