

Technical Bulletin

TCK119 & TCK323 - Read Before Installation

Please check crankshaft sprocket being removed matches the sprocket in this kit.

If the wrong crankshaft sprocket is fitted, the crankshaft pulley will be out of alignment preventing fitment of auxiliary drive belt(s).



TCK119
38mm
Sprocket



TCK323
33mm
Sprocket



Best Availability. Best Value.
Best Quality. Best Service.

TB0033