

Supersession Tensioner Pulley 531 0069 10 and 531 0071 10 by 531 0250 10

Manufacturer: Renault, Jeep

Model:

Model:	
• Renault	Espace, Fuego, Master, Trafic, 18, 20, 21, 25, 30
• Jeep	Cherokee, Comanche
Engine:	J8S 2.1 D, 2.1 TD
LuK AS Part No.:	531 0250 10
OE-No.:	77 00 871 169
	77 00 852 114 (replaced)
	77 00 722 452 (replaced)



Fig. 1: View of the replacement

a) Tensioner pulley 531 0071 10b) Tensioner pulley 531 0069 10

c) Tensioner pulley **531 0250 10**

The two tensioner pulleys **531 0069 10** and **531 0071 10** are no longer available and have been replaced by tensioner pulley **531 0250 10** (see **Fig. 1**).

The tensioner pulley **531 0250 10** is in two parts:

- Tensioner pulley with base plate
- Distance plate

The LuK AS range provides a belt drive toolbox (**400 0203 10**) and a timing belt tension meter (**400 0202 10**) for repairs to the drive train.



400 0202 10

400 0203 10



Fig. 2: Drive overview

Instructions for correct installation:

- **1.** Position the engine as directed by the manufacturer
- Remove the old tensioner pulley (the spring and sleeve are **not** required)
- **3.** Fit the new tensioner pulley (the old bolts can be re-used)
- **4.** Tension the timing belt with a suitable tool
- **5.** Tighten down the mounting bolts according to the manufacturer's directions
- 6. Turn the crankshaft by hand two
- 7. turns in the engine's direction of rotation
- **8.** Check the tension of the timing belt with a suitable tester and adjust as necessary (repeating steps 4 to 6)

Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 03.2008 INA 0018 Technical subject to change © 2008 LuK-Aftermarket Service oHG



 For further information:

 Phone:
 +44 (0) 14 32 264 264*

 Fax:
 +44 (0) 14 32 275 146

 Info@LuK-AS.co.uk
 www.Schaeffler-Aftermarket.com

 * Calls from within the UK 08457 001100