



Service Info



Visual differences

Over-running alternator pulley 535 0238 10

Manufacturer: Toyota

Model: Yaris

Model year: 11.2005 - 11.2008

Engine: 1.4D-4D

Part no.: 535 0238 10

OE number: 27415-33060



Image 1: Visual differences in over-running alternator pulley 535 0238 10



Image 2: INA special tool, part no. 400 0241 10

Two different over-running alternator pulley versions can be installed for Bosch alternators in the vehicles mentioned above.

Image 1 shows the production design (left) and the aftermarket design (right) of over-running alternator pulley 535 0238 10.

The two over-running alternator pulleys differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.

A special tool is required to remove and install the over-running alternator pulley (Image 2).

Observe the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com.

Phone: +44 (0) 14 32 264 264*
 Fax: +44 (0) 14 32 375 760
 info@luk-as.co.uk
 www.schaeffler-aftermarket.com

* Calls from within the UK 08457 001100

SCHAEFFLER
 AUTOMOTIVE AFTERMARKET

