



Service Info



Tensioner arm 534 0101 20

Higher force requirement for tensioner arm rotation

Manufacturer: Alfa, Fiat, Lancia

Models:

Alfa: 145, 146, 147, 156, GT
 Fiat: Brava, Bravo, Doblo, Idea, Marea, Multipla, Palio, Punto, Stilo, Strada
 Lancia: Lybra, Musa

Engines: 1.9 D

Part no.: 534 0101 20

For current listing refer to catalogue media



Fig. 2: Tensioner arm 534 0101 20 - new design



Fig. 1: Tensioner arm 534 0101 20 - old design

Schaeffler Automotive Aftermarket is offering a new tensioner arm for the vehicles listed (Fig. 2). In appearance it is nearly identical to the earlier design (Fig. 1).

When installing the V-ribbed belt in combination with this new design, however, the specific spring characteristics make it necessary to exert greater force in order to move it opposite the tensioning direction. Technically, this has no effect on the tensioning of the V-ribbed belt.

When installing the new tensioner arm, the screw supplied with the arm must be used.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264*
 Fax: +44 (0) 1432 375 760
 hfd-info@schaeffler.com
 www.schaeffler-aftermarket.co.uk

* Calls from within the UK 08457 001100

Issued 09.2016 INA 0155 Technical content subject to change
 OE Manufacturer's names and numbers are used for reference purposes only
 © 2016 Schaeffler Automotive Aftermarket GmbH & Co. KG

