



Service Info



Over-running alternator pulley 535 0303 10

Visual differences

Manufacturer: Toyota

Models: Auris, Corolla, Yaris

Engine: 1.4 Diesel

Part no.: 535 0303 10

OE number: 27415-33100

For current listing refer to catalogue media




Image: Visual differences in over-running alternator pulley 535 0303 10

Two different over-running alternator pulley versions can be installed for Denso alternators in the vehicles mentioned above.

The image shows the production design (left) and the aftermarket design (right) of over-running alternator pulley 535 0303 10.

The two over-running alternator pulleys differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.

A special tool is required to remove and install the over-running alternator pulley (e. g. SAAM Part no. 400 0444 10).

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264*

Fax: +44 (0) 1432 375 760

hfd-info@schaeffler.com

www.schaeffler-aftermarket.co.uk

* Calls from within the UK 08457 001100



SCHAEFFLER

REP>XPERT