

INA Service Info

•

Different slide rails

Design change during the construction period without clear delimitation

Manufacturer: Hyundai

Kia

Models: Accent III & IV

Elantra III, IV, V & VI

GETZ (TB) i10, i20, i30, i40 iX20, iX35 (Tucson)

CARENS III, IV & CEE'D (JD&ED), CRETA/CANTUS, CERATO I & III OPTIMA, RIO II-III, SOUL I, SPORTAGE,

TUCSON, VENGA

Item no. of


slide rails: 552 0167 10 (without mounting bracket)

552 0720 10 (with mounting bracket)

Item no. of timing chain

sets: 559 1863 30 (without mounting bracket)

559 1863 31 (with mounting bracket)



For the engines of the above vehicle models, the slide rails of the timing chain were changed during ongoing production between 2007 and 2012. For this reason, during a repair, different slide rails may be found. No clear delimitation regarding the model year or relevant engine generation was communicated by the vehicle manufacturer. Therefore, the item number of the replacement part cannot be defined until after the part installed in the vehicle has been inspected.

There are slide rails with and without mounting brackets. If a slide rail without a mounting bracket (figure 1) is being replaced, the item number 552 0167 10 must be used. Additionally, this slide rail is also contained in timing chain set 559 1863 30.

The sliding rail with mounting bracket (article number 552 0720 10, image 2) is not available individually. It is included in the timing chain kit with article number 559 1863 31.



Figure 1: Slide rail without mounting bracket item no.: 552 0167 10



Figure 2: Slide rail with mounting bracket item no.: 552 0720 10

Please observe the vehicle manufacturer specifications!

Phone: +44 (0) 1432 264 264 Fax: +44 (0) 1432 375 760 aftermarket.uk@schaeffler.com www.repxpert.co.uk

