

Blue Print

ADA102109, ADC42115, ADK82104, ADK82106, ADK82107, ADN12121



To fit:
Suzuki vehicles fitted with a diesel particulate filter, various models



EN

Oil Filter

Problem

The oil change reminder lamp is permanently illuminated and the driver misunderstands/ignores the warning lamp and continues to use the vehicle without changing the engine oil.

Cause

The engine oil on DPF equipped vehicles is excessively diluted by the fuel. The oil deteriorates and the viscosity is reduced, effecting its lubricating ability, which could lead to engine damage. This can be due to the vehicle being driven for short journeys and also driving long distances at slow speed. The vehicle recognises that the oil has deteriorated, then the oil change request warning lamp becomes illuminated to warn the driver to change the oil.

Solution

Replace the engine oil, filter, and reset the oil warning lamp.

For more technical information please visit: partsfinder.bilsteingroup.com