

Blue Print ADC47514, ADG07607

to fit:
Hyundai, Mitsubishi various models



EN

CAUTION FITTING TIMING BELT

This vehicle model is fitted with a manual AND viscous tensioner and it is **ESSENTIAL** that when fitting or tensioning the timing belt that the correct manufacturer's procedure is followed carefully. We recommend that a new viscous tensioner be fitted as a matter of course. However, if the original tensioner is to be used, the following additional care must be taken:

Compress the viscous tensioner SLOWLY, otherwise the hydraulic valves inside the unit will become distorted and cause the tensioner to 'over relax' after fitment. Take two or three minutes (using a workshop vice with protected jaws) to compress the tensioner.

Once fitted, check that the viscous tensioner protrusion is correct (3.8 - 4.8mm). **LEAVE FOR AT LEAST 15 MINUTES THEN RE-CHECK THE PROTRUSION.** If the protrusion has decreased, replace the tensioner.

A third check of the tensioner protrusion or belt tension is advisable after a longer period.

Blue Print recommend that the tensioner is replaced as a matter of course. If you have any doubt about the condition of the original viscous tensioner, it should also be replaced.



ADG07607
Timing Belt Tensioner assembly

For more technical information please visit: partsfinder.bilsteingroup.com