

Important to check the belt tensioner on the Corsa



Problem with the belt tensioner

The Opel Corsa linked for these compressors are known for a weak construction on the belt tensioner.

If the tensioner is not working properly, the belt may cause an overheating of the compressor and damage the clutch of the compressor.



→ For this reason, we highly recommend to check the belt tensioner and replace if needed. This operation is recommended by OE.

New reference including the belt tensioner

Borg always claims to deliver units “plug and play”. In order to make your life easier, we have created a new reference that includes the belt tensioner together with the AC compressor.

You can find it listed with the other two compressors for the same vehicles.



Furthermore, a warning label is now put on these units to remind to check the belt tensioner.



As the problem is not related to the quality of the compressor but to an external components, warranty claims for a broken hub will be rejected.