


# 29-9694 COMPRESSOR RELAY SERVICE BULLETIN



**ATTENTION**



**P-2871/P-3220**



**BMW 5-Series (E61)**

Relay located in the trunk of the vehicle under the spare tire compartment.

**INSTALLATION OF THIS AIR SUSPENSION COMPRESSOR REQUIRES THE REPLACEMENT OF THE COMPRESSOR RELAY.**

**FAILURE TO REPLACE THE OE RELAY WITH THE UNIT PROVIDED IN THIS KIT CAN CAUSE DAMAGE AND/OR VOID WARRANTY.**

PLEASE REFER TO YOUR VEHICLES SHOP MANUAL OR CONSULT YOUR LOCAL DEALERSHIP FOR THE LOCATION AND PROPER PROCEDURES FOR REPLACING YOUR AIR SUSPENSION COMPRESSOR RELAY.

**Arnott® is committed to the quality of its products. If you have a question or problem with any Arnott product, please contact Arnott by calling 800-251-8993 during normal business hours or email [techassistance@arnottinc.com](mailto:techassistance@arnottinc.com). (In the EU please call +31 (0)73 7850 580 or email [info@arnotteurope.com](mailto:info@arnotteurope.com))**