

ATTENTION




INSTALLATION OF THIS AIR SUSPENSION COMPRESSOR REQUIRES THE REPLACEMENT OF THE COMPRESSOR RELAY.

FAILURE TO REPLACE THE OE RELAY WITH THE UNIT PROVIDED IN THIS KIT CAN CAUSE DAMAGE AND/OR VOID WARRANTY.

PLEASE REFER TO YOUR VEHICLES SHOP MANUAL OR CONSULT YOUR LOCAL DEALERSHIP FOR ADDITIONAL INFORMATION AND PROPER PROCEDURES FOR REPLACING YOUR AIR SUSPENSION COMPRESSOR RELAY.

P-3220/P-3729




BMW 5 SERIES (E61)
Relay located in the trunk of the vehicle under the spare tire compartment.

P-4341




BMW X5 (F15)/X6 (F16)
Relay located in the trunk of the vehicle on the right side.

P-2985/P-3818



BMW 5 SERIES GT (F07)
Relay located in the trunk of the vehicle on the right side.



BMW 5 SERIES WAGON (F11)
Relay located in the trunk of the vehicle
beneath the floor.



BMW 7 SERIES (F01/02/04)
Relay located in the trunk of the vehicle on the right side.

2 11-21-10466 REV 03 May 9, 2023



Arnott US Business Office:

www.arnottinc.com

100 Sea Ray Drive Merritt Island, FL 32953

Call: 800.251.8993

321.868.3016

Fax: 321.868.3703

Email: techassistance@arnottinc.com

Arnott Europe Business Office:

www.arnotteurope.com

Docterskampstraat 1E/1F, 3 5222 AM 's-Hertogenbosch (NL)

NL Phone: +31 73 7850 580

DE Phone: +31 85 2087 438

UK Phone: +44 203 3186 124

BE Phone: +32 258 846 90

ES Phone: +34 91 901 10 56

FR Phone: +32 78 48 46 93

Email: info@arnotteurope.com



Air Springs



Struts



Shocks



Compressors



Dryers



Coil Spring Conversion Kits



Valve Blocks



Ride Height Sensors