

Important technical note relating to this unit

A known fault on the K12 Nissan Micra can result in incorrect diagnosis of a fault with the starter motor.

If the starter motor is not engaging when the ignition key is turned this is often due to a fault with the vehicles main fuse board, changing the starter motor relay does not fix the problem.

The fuse box needs replacing and also coding to the vehicles ECU