

## VKBA 3680

## Technical Bulletin – September 2015



Peugeot (307), Citroen (C4)



Caution, when mounting a HBU 1 bearing with different seals




SKF has several HBU 1 bearings containing a flat metal shield with an integrated rubber seal to be mounted on the inboard side and a double bended metal shield placed on the outboard side.

Note: If not mounted this way, you will decrease the lifetime of the bearing.

VKBA 3680 is packed with mounting instruction MI-542027 to highlight the importance of a visual check of both sides of the bearing before mounting.









Install confidence www.vsm.skf.com

