

Product Bulletin

Bulletin Number: 01-ROT-2022-EU

Issue date: 04/2022

DAN930 Alternator

New production site

The production site of DAN930 has been recently moved from DENSO Japan to DENSO Italy manufacturing plant in order to maximize the availability of this aftermarket fast-mover alternator by localization – *new Country of Origin is Italy.*

The DENSO Aftermarket catalogue part no remains the same, DAN930, whereas the DENSO Aftermarket technical code is substituted from 104210-2710 to 021080-2590.

Please be aware of a few appearance differences in new version 021080-2590 vs. old version 104210-2710 whilst full compatibility will be maintained.





021080-2590 (new version)

Lead frame new design without the 3 drain holes vs outside, internal labyrinth avoid direct contamination (no impact on cooling)



104210-2710 Old

104210-2710 (old version)

Lead frame old design with 3 drain holes vs outside through rear cover



Front view



021080-2590 New



104210-2710 Old

Rotor impregnation resin can be visible on fan randomly. (No impact for durability or contamination)

Nameplate label

DENSO catalog part no: DAN930 (no change)

DENSO technical code: 104210-2710 → 021080-2590

Country of Origin indication: Made in Japan \rightarrow Made in Italy



Further details of DENSO's starters and alternators range are available online at denso-am.eu, on TecDoc or from your local DENSO Aftermarket contact.

DENSO EUROPE B.V.

Hogeweyselaan 165 | 1382 JL Weesp | The Netherlands Tel. +31 (0)294 - 493 493 | Fax. +31 (0)294 - 417 122



