




## LuK Service Info



# Assembly note for LuK DMF

## Dual Mass Flywheel timing marks

Manufacturers:	Fiat Mercedes Nissan Opel Renault Vauxhall
Models:	
Fiat:	Talento
Mercedes:	Vito, Vivaro
Nissan:	NV300 Qashqai X-Trail
Renault:	Espace V Grand Scenic III & IV Megane III Scenic III & IV Traffic
Part no.:	415 0564 10 415 0796 10 415 1016 10



Picture 1: Hole in the DMF



Picture 2: Indent in the crank shaft

The Dual Mass Flywheel on these applications are fitted with a sensor ring. This must be timed correctly with the crankshaft for the vehicle to start and run correctly. As opposed to a conventional dowel pin, these are timed via a hole in the DMF (Picture 1) and an indent in the crank shaft (Picture 2).

Please observe the vehicle manufacturer specifications!

**You want more? We can help!**

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk