



# EXACT febi 100410



## to fit

Mercedes-Benz A-Class W169 A150,  
A160, A170, A180, A200

Mercedes-Benz B-Class W245 B150,  
B160, B170, B180, B200

Repl. no. 266 050 02 11 S3



EN

Chain tensioner, Gasket, 2 x M6 bolt, Sump plug, Gasket ring

## Chain tensioner for timing chains, with housing and fitting materials

### PROBLEM

Missing fitting materials and mountings are a widespread problem. Searching for and procuring the individual components costs time and money.

### CAUSE

The manufacturer recommends the replacement of all fitting materials when changing the chain tensioner febi 30548.

### SOLUTION

febi bilstein provides the complete solution under a single part number. febi 100410 is a complete set, containing six individual components in total, with all the parts required for a professional repair.

### ATTENTION

Replace the gasket and clean the sealing face. Tighten the M6 bolts with 8 Nm torque.

Register now for the official febi bilstein newsletter and receive the latest technical information automatically by email!

Further information may be obtained at: [www.febi.com](http://www.febi.com)